

HOLE No. : GW23  
 CO ORDINATES : E 69 250-00  
 LOCATION : MTG

N 16 114-19

JOB NO. : 221-60  
 RL : 361.63

drilling method	penetration	water	graphic log	scale (m)	Geological Log	Borehole Construction Details	bailing yield and additional observations
REVERSE CIRCULATION				0	Brown strongly oxidised fill	Cap	
				1		Cement grout	
				2			
				3			
				4	Lt grey semi psammitic schist		Backfill
				5			
				6			
				7			
				8			
				9			
				10			
				11			
				12			
				13			
				14	Dk grey semi psammitic schist		
				15			
				16	Lt grey semi psammitic schist		
				17			
				18			140mm Ø hole
				19		Cement grout	50mm Ø PVC pipe
				20			
				21			
				22		Bentonite	Backfill
				23			
				24		Gravel	50mm Ø PVC screen
				25			
				26			
				27			
			28			End Cap	

DRILL TYPE : SCHRAMM  
 FEED :  
 DRILLER : HOODS  
 COMMENCED : 30 6-92  
 COMPLETED :  
 LOGGED BY : IRF  
 CHECKED BY :  
 VERTICAL SCALE :

**KEY**  
 penetration  
 no resistance ranging to refusal

water  
 10.01.80  
 water level and date  
 water inflow  
 water outflow

CLIENT :  
 MACRAES MINING COMPANY LIMITED

PROJECT :  
 MACRAES EXTENDED PROJECT

GROUNDWATER INVESTIGATION  
 LOG OF BORE

Woodward-Clyde



DATE :  
 JULY 1992

DRAWING NO

FIGURE NO